

































Asko 136





COLLI 1/3				
E+G	500	x	381	2
J+K	500	x	381	2
D	494	x	380	2
P	494	x	379	1
A	1102	x	400	1
H	560	x	399	1
COLLI 2/3				
T	1300	x	600	1
L	494	x	70	2
M	494	x	70	2
S	1103	x	364	1
R	1103	x	364	1
V	1283	x	168	1
W	1016	x	168	1
A1+B1	320	x	100	6
COLLI 3/3				
U	728	x	599	1
F	520	x	163	3
N	526	x	60	2
B+C	560	x	250	2
D1	318	x	473	3
C1	463	x	100	3

 1x 0013K	 ø12 6x 0094K	 ø15 41x 0018K	 39x 0019K	 4x 0074K
 7x50 17x 0005V	 3x20 22x 0007V	 4x 0119K	 3,5x16 12x 0002V	 M4x10 6x 0006K
 4,5x35 12x 0011V	 4x30 8x 0012V	 4x 0042K	 6x 0004K	 4x30 6x 0004V
 8x40 36x 0001K	 8x60 2x 0034K	 ø20 8x 0054K	 ø20 17x 0055K	 ø20 17x 0056K
 11x 0002K	 3x 0018U	 6x 0024K	 1x 0011K	
				


1)



2)






0019K



3)



3,5x16 12x
0002V

6x 0024K





4)



8x
ø15 0018K




5)




6)




7)




8)








9)





II.





10)



3x20  0007V	6x  0002K	3x 8x40  0001K	3x  0001K	8x  0055K	8x ø15  0018K	4x  0074K
---	---	---	---	---	--	---



11)




12)



13)

I.




3x



0011V

0011V




II.





III.




IV.




V.




0011V




0094K




0054K



0004K



0018U



0004V



14)

M4x10

6x



0006K




15)

8x40

7x

0001K



16)

3x20

4x



0007V

2x



0002K

11x




0019K




17)







18)




19)



  2x ø20 0054K	  5x ø20 0055K	 7x ø15 0018K
---	---	--





Bezpečnostní list / Bezpečnostný list

